Visual changes:



IEC 62368-1 compliance due to:

- UL 94 V-0 materials
- component certification according to IEC 61984